# CROSSBERRY

# Installation Instruction
## Gecko

295   80

610

2-11x18

120

⚠

Attentions:
1. The products should be installed and maintained by qualified professionals, could not change the product inner structure or parts by yourself. During the period of installation or maintenance, ensure the electricity is off. Ensure the products earth-wired reliably.
2. Pls do not open the back cover and the wire fixing connectors during usage, meanwhile,make the waterproof treatment of the wire connecting places, otherwise, the product will be damaged by water in due to inproper operation;
3.The LED light source should be replaced by manufactuer,service agent or professional qualified technicans;
4. The shell of the product will reach high temperature when using or after using, so it could not be covered with thermal insulation materials

Preparation before installation:
outer hexagon wrench, waterproof-insulating tape, cross screwdriver

1. Fix the bracket onto the surface of the installation place

2. Adjust the lighting angle according to your requirement, then tighten the fixing screws

L   L
PE   PE   AC
N   N   120V-277V

3. wiring according to the diagram